

# SAFETY WARNING



- Drive fasteners into appropriate work surfaces only. Never shoot into materials too hard to penetrate or materials too soft to allow a fastener to drive through and exit the material.
- Do not actuate the tool unless the tool is placed firmly against the work surface.
- Fully release the trigger after each shot is fired to properly cycle the piston, and never continually depress trigger.
- Never depress the trigger unless the tool and nosepiece is depressed against the work surface.

## Safe Actuating Sequence:

1. Depress the nosepiece of the tool against the work surface.
2. Completely depress the trigger to actuate the tool.
3. Release the trigger before lifting the tool from work surface.



Never depress the trigger unless tool is against work surface.

